## Flight Information

| Flight Number<br>ID2625          | Aircraft<br>PK-ABC (I   | B737-800)               | Date<br>12/01/2025         |
|----------------------------------|---|-------------------------|----------------------------|
| Departure<br><b>CGK</b><br>04:11 |   | Arrival<br>DPS<br>06:38 |                            |
| Flight Time<br>2.4 hrs           | Block Time<br>2.9 hrs   | Night Time<br>1.0 hrs   | Instrument Time<br>0.0 hrs |
| Crew Informa                     | tion  |                         |                            |
| SIC: Jane Doe                    | <b>th</b><br>s   Duty Time: 3.9 hrs<br>s   Duty Time: 3.9 hrs |                         |                            |
| Bob Wilson                       | s   Duty Time: 4.4 hrs<br>s   Duty Time: 4.4 hrs              |                         |                            |

## **Engine Data**

| Engine | Oil Uplift | N1 (%) | N2 (%) | EGT (°C) | Oil Press |
|--------|------------|--------|--------|----------|-----------|
| 1      | 3          | 93     | 91     | 586      | 47        |
| 2      | 3          | 92     | 92     | 593      | 46        |

## Defects

| Description                               | Category | Status | Action Taken |
|---|----------|--------|--------------|
| Cabin overhead light flickering in row 15 | Cabin    | open   | -            |

abin

Generated on 17/01/2025 09:06 | Flight Log #FL00026